

<b>Nome Articolo</b>	<b>Posizione</b>	<b>( ) - O</b>	<b>Albero</b>	<b>Sede</b>	<b>Lunghezza</b>	<b>Entro Bordo</b>
<b>Acme AL 800</b>	<b>Biella</b>	<b>( )</b>	<b>50,00</b>	<b>58,00</b>	<b>60,00</b>	<b>50,00</b>
<b>Alfa Romeo Giulia 1006</b>	<b>Banco Intermedio</b>	<b>(</b>		<b>67,00</b>		<b>20,00</b>
<b>Allis - CHALMERS</b>	<b>Biella</b>	<b>( )</b>	<b>69,91</b>	<b>77,80</b>	<b>47,75</b>	
<b>Allis - CHALMERS</b>	<b>Banco</b>	<b>O</b>	<b>88,96</b>	<b>96,85</b>	<b>30,30</b>	
<b>Arona A8-FA 20</b>	<b>Banco Centrale</b>	<b>( )</b>	<b>80,00</b>	<b>90,00</b>	<b>42,00</b>	
<b>Arona CC290</b>	<b>Biella</b>	<b>( )</b>	<b>58,74</b>	<b>62,42</b>	<b>24,60</b>	
<b>Arona Diesel D4</b>	<b>Biella</b>	<b>( )</b>	<b>48,00</b>	<b>57,00</b>	<b>45,00</b>	
<b>Arona Diesel DA 10</b>	<b>Biella</b>	<b>( )</b>	<b>53,00</b>	<b>63,00</b>	<b>45,00</b>	
<b>Arona Diesel DA 10</b>	<b>Banco Centrale</b>	<b>( )</b>	<b>63,00</b>	<b>70,00</b>	<b>45,00</b>	
<b>Arona M8-FA 10</b>	<b>Biella</b>	<b>( )</b>	<b>73,00</b>	<b>84,00</b>	<b>53,00</b>	<b>47,00</b>
<b>Bernard M5</b>	<b>Biella</b>	<b>( )</b>	<b>40,00</b>	<b>43,70</b>	<b>47,50</b>	
<b>Beta B200</b>	<b>Biella</b>	<b>( )</b>	<b>25,00</b>	<b>30,00</b>	<b>23,00</b>	<b>19,00</b>
<b>Bungartz HATZ-E85</b>	<b>Biella</b>	<b>( )</b>	<b>50,00</b>	<b>58,00</b>	<b>38,00</b>	<b>26,00</b>
<b>Carraro Trattore 335</b>	<b>Biella</b>	<b>( )</b>	<b>69,87</b>	<b>73,72</b>	<b>36,45</b>	
<b>Carraro Trattore 335</b>	<b>Biella</b>	<b>( )</b>	<b>69,87</b>	<b>73,72</b>	<b>36,45</b>	
<b>Carraro Trattore 335</b>	<b>Banco</b>	<b>( )</b>	<b>69,82</b>	<b>74,09</b>	<b>40,76</b>	
<b>Carraro Trattore C23</b>	<b>Biella</b>	<b>( )</b>	<b>55,35</b>	<b>59,09</b>	<b>30,00</b>	
<b>Carraro Trattore C23</b>	<b>Banco</b>	<b>( )</b>	<b>64,99</b>	<b>68,72</b>	<b>30,00</b>	
<b>Carraro Trattore C23</b>	<b>Banco</b>	<b>( )</b>	<b>69,82</b>	<b>74,10</b>	<b>35,76</b>	
<b>Carraro Trattore C23</b>	<b>Banco</b>	<b>( )</b>	<b>69,82</b>	<b>74,10</b>	<b>35,76</b>	
<b>Carraro Trattore C23</b>	<b>Banco</b>	<b>( )</b>	<b>69,82</b>	<b>74,10</b>	<b>35,76</b>	
<b>Carraro Trattore C23</b>	<b>Banco</b>	<b>( )</b>	<b>69,82</b>	<b>74,10</b>	<b>35,76</b>	
<b>Carraro Trattore C23</b>	<b>Rasamento</b>	<b>( )</b>	<b>75,50</b>	<b>90,40</b>	<b>03,17</b>	
<b>Caterpillar D5 D6</b>	<b>Biella</b>	<b>( )</b>	<b>47,71</b>	<b>50,85</b>	<b>25,40</b>	
<b>Caterpillar D7 D11</b>	<b>Banco Anteriore</b>	<b>O</b>	<b>54,07</b>	<b>66,70</b>	<b>50,75</b>	<b>38,00</b>

<b>Caterpillar D7 D11</b>	<b>Banco Anteriore</b>	<b>( )</b>	<b>54,07</b>	<b>66,70</b>	<b>54,00</b>	<b>41,00</b>
<b>Caterpillar D7 D11</b>	<b>Banco Posteriore</b>	<b>0</b>	<b>54,07</b>	<b>66,70</b>	<b>52,30</b>	
<b>Caterpillar D7 D11</b>	<b>Banco Posteriore</b>	<b>( )</b>	<b>54,07</b>	<b>66,70</b>	<b>52,40</b>	
<b>Caterpillar D7 D11</b>	<b>Biella</b>	<b>( )</b>	<b>50,87</b>	<b>54,70</b>	<b>45,00</b>	
<b>Demm LA NOVA</b>	<b>Biella</b>	<b>( )</b>	<b>55,04</b>	<b>58,75</b>	<b>31,40</b>	
<b>Demm LA NOVA</b>	<b>Banco Ant/Post</b>	<b>( )</b>	<b>60,45</b>	<b>65,20</b>	<b>43,40</b>	
<b>Demm LA NOVA</b>	<b>Banco Intermedio</b>	<b>( )</b>	<b>60,45</b>	<b>65,20</b>	<b>31,40</b>	
<b>Deutz F 1L 812</b>	<b>Banco</b>	<b>( )</b>	<b>69,99</b>	<b>74,51</b>	<b>27,00</b>	
<b>Deutz F 2L612/712</b>	<b>Biella</b>	<b>( )</b>	<b>59,99</b>	<b>66,02</b>	<b>25,00</b>	
<b>Deutz F 2L612/712</b>	<b>Banco Ant/Post</b>	<b>0</b>	<b>61,99</b>	<b>75,02</b>	<b>30,00</b>	
<b>Deutz F 2L612/712</b>	<b>Banco Centrale</b>	<b>( )</b>	<b>64,99</b>	<b>80,02</b>	<b>35,80</b>	<b>28,00</b>
<b>Deutz F 4L514</b>	<b>Banco Posteriore</b>	<b>( )</b>	<b>75,00</b>	<b>90,00</b>	<b>46,00</b>	<b>35,00</b>
<b>Deutz F 4L514</b>	<b>Banco Intermedio</b>	<b>( )</b>	<b>75,00</b>	<b>90,00</b>	<b>43,00</b>	<b>35,00</b>
<b>Deutz F 4L514</b>	<b>Biella</b>	<b>( )</b>	<b>75,00</b>	<b>85,00</b>	<b>45,90</b>	<b>40,00</b>
<b>Deutz FL 612</b>	<b>Banco Anteriore</b>	<b>( )</b>	<b>70,00</b>	<b>77,00</b>	<b>28,00</b>	
<b>Deutz FL 612</b>	<b>Banco Ant/Post</b>	<b>( )</b>	<b>62,00</b>	<b>75,00</b>	<b>34,00</b>	
<b>Deutz FL 612</b>	<b>Banco Centrale</b>	<b>( )</b>	<b>62,00</b>	<b>80,00</b>	<b>36,00</b>	<b>28,00</b>
<b>Ducati 350/500</b>	<b>Biella</b>	<b>( )</b>	<b>40,00</b>	<b>43,65</b>	<b>19,00</b>	
<b>Ducati Diesel</b>	<b>Biella</b>	<b>( )</b>	<b>47,30</b>	<b>51,60</b>	<b>19,00</b>	
<b>Ducati Diesel</b>	<b>Banco Anteriore</b>	<b>0</b>	<b>46,00</b>	<b>52,00</b>	<b>23,00</b>	
<b>Ducati Diesel</b>	<b>Banco Posteriore</b>	<b>0</b>	<b>46,00</b>	<b>52,00</b>	<b>27,00</b>	
<b>Ducati Diesel</b>	<b>Banco</b>	<b>0</b>	<b>50,00</b>	<b>58,00</b>	<b>22,90</b>	
<b>Euro Diesel</b>	<b>Biella</b>	<b>( )</b>	<b>55,42</b>	<b>59,09</b>	<b>27,00</b>	
<b>Euro Diesel</b>	<b>Banco</b>	<b>( )</b>	<b>52,00</b>	<b>57,00</b>	<b>30,00</b>	
<b>Falco HP10</b>	<b>Biella</b>	<b>( )</b>	<b>40,00</b>	<b>48,00</b>	<b>35,00</b>	<b>28,00</b>
<b>Falco HP4</b>	<b>Biella</b>	<b>( )</b>	<b>30,00</b>	<b>35,00</b>	<b>24,00</b>	<b>20,00</b>

<b>Falco HP8</b>	<b>Biella</b>	<b>( )</b>	<b>36,00</b>	<b>42,00</b>	<b>30,00</b>	<b>24,00</b>
<b>Ferguson TF20</b>	<b>Biella</b>	<b>( )</b>	<b>53,00</b>	<b>56,73</b>	<b>24,60</b>	
<b>Ferguson TF20</b>	<b>Banco Ant/Cent/Post</b>	<b>( )</b>	<b>63,00</b>	<b>66,70</b>	<b>38,10</b>	
<b>Ferguson TF20 Diesel</b>	<b>Biella</b>	<b>( )</b>	<b>58,70</b>	<b>62,45</b>	<b>31,00</b>	
<b>Ferguson TF20 Diesel</b>	<b>Banco Ant/centr</b>	<b>( )</b>	<b>69,86</b>	<b>74,10</b>	<b>38,23</b>	
<b>Ferguson TF20 Diesel</b>	<b>Banco Posteriore</b>	<b>( )</b>	<b>69,90</b>	<b>74,15</b>	<b>40,55</b>	
<b>Fiat 500 Anelli sotto canna</b>		<b>0</b>	<b>81,50</b>			
<b>Fiat 500 Anelli sotto canna</b>		<b>0</b>	<b>83,00</b>			
<b>Gueldner 2BN-2BNS</b>	<b>Biella</b>	<b>( )</b>	<b>70,05</b>	<b>78,02</b>	<b>38,00</b>	
<b>Gueldner 2BN-2BNS</b>	<b>Banco Anteriore</b>	<b>( )</b>	<b>70,05</b>	<b>90,04</b>	<b>40,00</b>	<b>35,00</b>
<b>Gueldner 2BN-2BNS</b>	<b>Banco Posteriore</b>	<b>( )</b>	<b>90,07</b>	<b>105,05</b>	<b>38,00</b>	
<b>Gueldner 2LD</b>	<b>Banco Ant/centr</b>	<b>( )</b>	<b>70,05</b>	<b>90,05</b>	<b>35,00</b>	<b>30,00</b>
<b>Gueldner GK</b>	<b>Banco Anteriore</b>	<b>( )</b>	<b>55,00</b>	<b>70,05</b>	<b>33,00</b>	
<b>Gueldner GK</b>	<b>Banco Posteriore</b>	<b>( )</b>	<b>65,00</b>	<b>80,05</b>	<b>28,00</b>	
<b>Guidetti Condor DA600</b>	<b>Biella</b>	<b>( )</b>	<b>48,02</b>	<b>51,00</b>	<b>28,00</b>	
<b>Hanomag</b>	<b>Biella</b>	<b>( )</b>	<b>50,00</b>	<b>54,00</b>	<b>22,00</b>	
<b>Hanomag</b>	<b>Banco Ant/centr</b>	<b>( )</b>	<b>64,00</b>	<b>68,00</b>	<b>25,00</b>	
<b>Hanomag</b>	<b>Banco Posteriore</b>	<b>( )</b>	<b>64,00</b>	<b>68,00</b>	<b>35,00</b>	<b>31,00</b>
<b>Hanomag R35</b>	<b>Banco Intermedio</b>	<b>( )</b>	<b>70,00</b>	<b>85,00</b>	<b>30,00</b>	
<b>Hanomag R35</b>	<b>Banco Posteriore</b>	<b>( )</b>	<b>70,00</b>	<b>85,00</b>	<b>48,00</b>	<b>40,00</b>
<b>Jenbach JW20</b>	<b>Biella</b>	<b>( )</b>	<b>75,09</b>	<b>85,07</b>	<b>43,00</b>	
<b>Jozzelli R4655</b>	<b>Biella</b>	<b>( )</b>	<b>22,00</b>	<b>28,00</b>	<b>23,00</b>	<b>18,00</b>
<b>Jozzelli R4675</b>	<b>Biella</b>	<b>( )</b>	<b>30,00</b>	<b>38,00</b>	<b>30,00</b>	<b>23,00</b>
<b>Lamborghini Trattore</b>	<b>Biella</b>	<b>( )</b>	<b>70,00</b>	<b>78,00</b>	<b>48,00</b>	<b>36,00</b>
<b>Lamborghini Trattore</b>	<b>Banco</b>	<b>( )</b>	<b>101,00</b>	<b>116,00</b>	<b>40,00</b>	<b>30,00</b>
<b>Lamborghini Trattore DLA35</b>	<b>Banco Centrale</b>	<b>( )</b>	<b>60,00</b>	<b>68,04</b>	<b>46,00</b>	<b>32,00</b>

<b>Lamborghini Trattore DLA35</b>	<b>Biella</b>	<b>()</b>	<b>57,09</b>	<b>60,84</b>	<b>33,00</b>	
<b>Lamborghini Trattore R240</b>	<b>Biella</b>	<b>()</b>	<b>59,93</b>	<b>63,67</b>	<b>25,53</b>	
<b>Lamborghini Trattore R240</b>	<b>Banco</b>	<b>()</b>	<b>69,84</b>	<b>74,09</b>	<b>25,40</b>	
<b>Lamborghini Trattore R240</b>	<b>Banco</b>	<b>()</b>	<b>69,84</b>	<b>74,09</b>	<b>25,40</b>	
<b>Lamborghini Trattore R240</b>	<b>Banco</b>	<b>()</b>	<b>69,84</b>	<b>74,09</b>	<b>25,40</b>	
<b>Lamborghini Trattore R704</b>	<b>Biella/Banco</b>	<b>()</b>	<b>67,95</b>	<b>71,74</b>	<b>36,00</b>	
<b>Landini R3000 R4000</b>	<b>Banco Anteriore</b>		<b>69,90</b>	<b>74,10</b>	<b>33,15</b>	
<b>Landini R3000 R4000</b>	<b>Banco Posteriore</b>		<b>69,90</b>	<b>74,10</b>	<b>40,75</b>	
<b>Landini R3000 R4000</b>	<b>Banco Intermedio</b>		<b>69,90</b>	<b>74,10</b>	<b>25,40</b>	
<b>Landini R3000 R4000</b>	<b>Biella</b>	<b>()</b>	<b>57,20</b>	<b>60,85</b>	<b>30,20</b>	
<b>Lombardini Boccola Albero Distr</b>			<b>48,50</b>	<b>54,04</b>	<b>30,00</b>	
<b>Lombardini LA 400/490</b>	<b>Biella</b>	<b>()</b>	<b>35,00</b>	<b>38,11</b>	<b>27,03</b>	
<b>Lombardini LA 80/82</b>	<b>Biella</b>	<b>()</b>	<b>30,00</b>	<b>33,00</b>	<b>20,00</b>	
<b>Lombardini LA250</b>	<b>Biella</b>	<b>()</b>	<b>28,00</b>	<b>31,00</b>	<b>17,00</b>	
<b>Lombardini LA4</b>	<b>Biella</b>	<b>()</b>	<b>30,00</b>	<b>38,00</b>	<b>34,50</b>	<b>29,00</b>
<b>Lombardini LA54/60</b>	<b>Biella</b>	<b>()</b>	<b>25,00</b>	<b>32,00</b>	<b>24,50</b>	<b>16,00</b>
<b>Lombardini LA65</b>	<b>Biella</b>	<b>()</b>	<b>25,00</b>	<b>28,00</b>	<b>20,00</b>	
<b>Lombardini LA65/58</b>	<b>Biella</b>	<b>()</b>	<b>25,00</b>	<b>28,00</b>	<b>18,00</b>	
<b>Lombardini LA70/75</b>	<b>Biella</b>	<b>()</b>	<b>25,00</b>	<b>33,00</b>	<b>29,50</b>	<b>24,00</b>
<b>Lombardini LA85/85</b>	<b>Biella</b>	<b>()</b>	<b>35,00</b>	<b>38,11</b>	<b>21,28</b>	
<b>Lombardini LA90</b>	<b>Biella</b>	<b>()</b>	<b>33,00</b>	<b>40,00</b>	<b>34,50</b>	<b>28,00</b>
<b>Lombardini LDA 500/520/530</b>	<b>Biella</b>	<b>()</b>	<b>40,00</b>	<b>43,65</b>	<b>21,00</b>	
<b>Lombardini LDA 500/520/530</b>	<b>Banco Posteriore</b>	<b>0</b>	<b>40,00</b>	<b>44,00</b>	<b>30,00</b>	
<b>Lombardini LDA 500/520/530</b>	<b>Rasamento</b>	<b>()</b>	<b>47,00</b>	<b>65,00</b>	<b>2,36</b>	
<b>Lombardini LDA 560</b>	<b>Biella</b>	<b>()</b>	<b>45,50</b>	<b>48,60</b>	<b>21,00</b>	
<b>Lombardini LDA 560</b>	<b>Banco</b>	<b>0</b>	<b>55,00</b>	<b>60,00</b>	<b>34,00</b>	

<b>Lombardini LDA 560</b>	<b>Banco</b>	<b>0</b>	<b>72,15</b>	<b>77,02</b>	<b>26,20</b>	
<b>Lombardini LDA 672/673/674</b>	<b>Banco Ant/Post</b>	<b>0</b>	<b>59,95</b>	<b>65,03</b>	<b>30,12</b>	
<b>Lombardini LDA 672/673/674</b>	<b>Banco Centrale</b>	<b>( )</b>	<b>59,95</b>	<b>63,67</b>	<b>27,00</b>	
<b>Lombardini LDA 672/673/674</b>	<b>Rasamento</b>	<b>( )</b>	<b>65,80</b>	<b>82,60</b>	<b>2,36</b>	
<b>Lombardini LDA 700/710/713</b>	<b>Biella</b>	<b>( )</b>	<b>50,00</b>	<b>53,70</b>	<b>21,30</b>	
<b>Lombardini LDA 700/710/713</b>	<b>Biella</b>	<b>( )</b>	<b>50,00</b>	<b>53,70</b>	<b>21,30</b>	
<b>Lombardini LDA 700/710/713/72</b>	<b>Banco</b>	<b>0</b>	<b>45,05</b>	<b>50,02</b>	<b>30,25</b>	
<b>Lombardini LDA 75/450/510</b>	<b>Biella</b>	<b>( )</b>	<b>42,00</b>	<b>45,71</b>	<b>27,00</b>	
<b>Lombardini LDA 75/450/510</b>	<b>Banco LD</b>	<b>0</b>	<b>42,05</b>	<b>54,05</b>	<b>27,00</b>	
<b>Lombardini LDA 75/450/510</b>	<b>Banco LV</b>	<b>0</b>	<b>40,05</b>	<b>53,05</b>	<b>27,00</b>	
<b>Lombardini LDA 75/91 Portina E</b>	<b>Banco</b>	<b>0</b>	<b>30,07</b>	<b>40,04</b>	<b>17,00</b>	
<b>Lombardini LDA 75/91 Portina E</b>	<b>Banco</b>	<b>0</b>	<b>30,07</b>	<b>40,04</b>	<b>20,00</b>	
<b>Lombardini LDA 78</b>	<b>Banco Centrale</b>	<b>0</b>	<b>60,05</b>	<b>68,00</b>	<b>33,00</b>	<b>27,00</b>
<b>Lombardini LDA 832/833/834</b>	<b>Banco Anteriore</b>	<b>0</b>	<b>64,97</b>	<b>70,03</b>	<b>35,00</b>	
<b>Lombardini LDA 832/833/834</b>	<b>Banco Posteriore</b>	<b>0</b>	<b>64,97</b>	<b>70,03</b>	<b>28,00</b>	
<b>Lombardini LDA 832/833/834</b>	<b>Banco Centrale</b>	<b>( )</b>	<b>64,97</b>	<b>68,73</b>	<b>27,00</b>	
<b>Lombardini LDA 904</b>	<b>Banco Ant/Post</b>	<b>0</b>	<b>55,00</b>	<b>60,02</b>	<b>28,25</b>	
<b>Lombardini LDA 904</b>	<b>Banco Centrale</b>	<b>( )</b>	<b>55,35</b>	<b>59,09</b>	<b>21,00</b>	
<b>Lombardini LDA 904</b>	<b>Banco Ant/Post</b>	<b>0</b>	<b>55,00</b>	<b>60,02</b>	<b>28,25</b>	
<b>Lombardini LDA 91/96/97/100</b>	<b>Biella</b>	<b>( )</b>	<b>55,42</b>	<b>59,09</b>	<b>27,00</b>	
<b>Lombardini LDA 96/97/100</b>	<b>Banco</b>	<b>0</b>	<b>45,01</b>	<b>57,01</b>	<b>33,00</b>	
<b>Mag Bucher</b>	<b>Biella</b>	<b>( )</b>	<b>35,00</b>	<b>38,20</b>	<b>33,00</b>	
<b>Moto Meccanica Trattore</b>	<b>Banco Ant/centr</b>		<b>75,00</b>	<b>85,00</b>	<b>38,00</b>	
<b>Moto Meccanica Trattore</b>	<b>Banco Posteriore</b>		<b>75,00</b>	<b>85,00</b>	<b>60,00</b>	<b>50,00</b>
<b>Nuffield BMC</b>	<b>Biella</b>	<b>( )</b>	<b>61,96</b>	<b>67,05</b>	<b>31,00</b>	
<b>Nuffield BMC</b>	<b>Banco Intermedio</b>		<b>77,85</b>	<b>84,20</b>	<b>28,65</b>	

<b>Oria DV 400</b>	<b>Banco</b>		<b>55,00</b>	<b>70,00</b>	<b>29,00</b>	
<b>Oria DV 500</b>	<b>Banco</b>	<b>0</b>	<b>52,00</b>	<b>62,00</b>	<b>32,00</b>	
<b>Oria DV 500/550</b>	<b>Biella</b>	<b>( )</b>	<b>53,03</b>	<b>56,73</b>	<b>29,46</b>	
<b>Oria DV 500/550</b>	<b>Banco Anteriore</b>		<b>55,02</b>	<b>65,00</b>	<b>32,00</b>	
<b>Oria DV 650/700</b>	<b>Banco Ant/Post</b>	<b>0</b>	<b>60,00</b>	<b>75,00</b>	<b>36,00</b>	
<b>Palmieri Diesel</b>	<b>Banco Posteriore</b>	<b>0</b>	<b>65,00</b>	<b>80,05</b>	<b>27,00</b>	
<b>Perkins</b>	<b>Biella</b>		<b>57,20</b>	<b>63,50</b>	<b>39,45</b>	<b>35,70</b>
<b>Perkins Pyton P3</b>	<b>Biella</b>	<b>( )</b>	<b>57,18</b>	<b>60,85</b>	<b>30,20</b>	
<b>Perkins Pyton P3</b>	<b>Banco Anteriore</b>	<b>( )</b>	<b>69,90</b>	<b>76,20</b>	<b>33,35</b>	
<b>Perkins Pyton P3</b>	<b>Banco Posteriore</b>	<b>( )</b>	<b>69,90</b>	<b>76,20</b>	<b>47,60</b>	<b>38,10</b>
<b>Perkins Pyton P3</b>	<b>Banco Intermedio</b>	<b>( )</b>	<b>69,90</b>	<b>76,20</b>	<b>25,40</b>	
<b>Perkins Pyton P3</b>	<b>Banco Centrale</b>	<b>( )</b>	<b>69,90</b>	<b>76,20</b>	<b>41,27</b>	
<b>Raimondi RCM60</b>	<b>Biella</b>		<b>64,00</b>	<b>72,00</b>	<b>35,00</b>	
<b>Raimondi RCM60</b>	<b>Banco Anteriore</b>		<b>70,10</b>	<b>78,06</b>	<b>48,00</b>	
<b>Raimondi RCM60</b>	<b>Banco Intermedio</b>		<b>70,10</b>	<b>78,06</b>	<b>30,00</b>	
<b>Raimondi RCM60</b>	<b>Banco Posteriore</b>		<b>70,10</b>	<b>78,06</b>	<b>53,70</b>	<b>35,00</b>
<b>Raimondi Leprotto RCT26</b>	<b>Biella</b>		<b>60,00</b>	<b>68,00</b>	<b>65,00</b>	
<b>Raimondi Leprotto RCT4</b>	<b>Biella</b>		<b>50,00</b>	<b>62,00</b>	<b>60,00</b>	
<b>Royal Enfield</b>	<b>Biella</b>		<b>57,00</b>	<b>65,00</b>	<b>25,00</b>	
<b>Royal Enfield</b>	<b>Banco</b>		<b>44,50</b>	<b>60,50</b>	<b>42,00</b>	<b>70,00</b>
<b>Royal Enfield</b>	<b>Banco</b>		<b>44,50</b>	<b>60,50</b>	<b>66,00</b>	<b>70,00</b>
<b>Ruggerini MD75/150/190</b>	<b>Biella</b>	<b>( )</b>	<b>40,00</b>	<b>43,66</b>	<b>22,00</b>	
<b>Ruggerini MD75/150/190</b>	<b>Banco Ant/Post</b>	<b>( )</b>	<b>45,00</b>	<b>49,85</b>	<b>24,00</b>	
<b>Ruggerini CRD 100</b>	<b>Banco Posteriore</b>	<b>0</b>	<b>50,00</b>	<b>65,03</b>	<b>34,00</b>	
<b>Ruggerini CRD 100</b>	<b>Banco Anteriore</b>	<b>0</b>	<b>45,00</b>	<b>56,02</b>	<b>53,00</b>	
<b>Ruggerini CRD 100</b>	<b>Banco Centrale</b>	<b>( )</b>	<b>58,74</b>	<b>62,42</b>	<b>36,00</b>	

<b>Ruggerini RA10</b>	<b>Biella</b>	<b>( )</b>	<b>40,00</b>	<b>50,00</b>	<b>50,00</b>	<b>42,00</b>
<b>Ruggerini RA65</b>	<b>Biella</b>	<b>( )</b>	<b>25,00</b>	<b>33,00</b>	<b>30,00</b>	<b>24,00</b>
<b>Ruggerini RA80</b>	<b>Biella</b>	<b>( )</b>	<b>40,01</b>	<b>43,67</b>	<b>24,38</b>	
<b>Ruggerini RA85</b>	<b>Biella</b>	<b>( )</b>	<b>35,00</b>	<b>38,11</b>	<b>32,00</b>	
<b>Ruggerini RD85</b>	<b>Biella</b>	<b>( )</b>	<b>45,00</b>	<b>48,01</b>	<b>24,12</b>	
<b>Ruggerini RD85</b>	<b>Banco</b>	<b>0</b>	<b>42,09</b>	<b>50,04</b>	<b>40,20</b>	
<b>Ruggerini RD901</b>	<b>Banco</b>	<b>( )</b>	<b>45,00</b>	<b>47,98</b>	<b>24,12</b>	
<b>Ruggerini RD95</b>	<b>Biella</b>	<b>( )</b>	<b>58,74</b>	<b>42,42</b>	<b>24,71</b>	
<b>Ruggerini RD95</b>	<b>Banco Ant/Post</b>	<b>0</b>	<b>45,01</b>	<b>56,08</b>	<b>51,00</b>	
<b>Sachs</b>	<b>Biella</b>		<b>48,00</b>	<b>53,00</b>	<b>37,00</b>	
<b>Sachs</b>	<b>Biella</b>		<b>60,00</b>	<b>66,09</b>	<b>36,50</b>	
<b>Same 1/6 Cil.</b>	<b>Biella</b>	<b>( )</b>	<b>67,95</b>	<b>71,74</b>	<b>48,17</b>	
<b>Same 1/6 Cil.</b>	<b>Banco</b>	<b>( )</b>	<b>70,00</b>	<b>74,00</b>	<b>67,00</b>	
<b>Same Saturno</b>	<b>Biella</b>	<b>( )</b>	<b>67,95</b>	<b>71,74</b>	<b>27,00</b>	
<b>Same Saturno</b>	<b>Banco</b>	<b>( )</b>	<b>70,00</b>	<b>74,00</b>	<b>32,00</b>	
<b>Same Solar Frutteto</b>	<b>Biella</b>	<b>( )</b>	<b>63,50</b>	<b>67,22</b>	<b>29,00</b>	
<b>Same Trattore DA952V</b>	<b>Biella</b>	<b>( )</b>	<b>67,95</b>	<b>71,74</b>	<b>24,00</b>	
<b>Same Trattore DA952V</b>	<b>Banco</b>	<b>( )</b>	<b>70,00</b>	<b>74,00</b>	<b>50,00</b>	
<b>Same Trattore DA952V</b>	<b>Banco</b>	<b>( )</b>	<b>70,00</b>	<b>74,00</b>	<b>40,00</b>	
<b>Schluter</b>	<b>Biella</b>		<b>75,07</b>	<b>85,05</b>	<b>59,90</b>	<b>44,00</b>
<b>Schluter</b>	<b>Banco</b>		<b>70,07</b>	<b>90,05</b>	<b>55,00</b>	
<b>Schluter</b>	<b>Banco</b>		<b>65,07</b>	<b>85,05</b>	<b>43,00</b>	
<b>Slanzi DV 3150R</b>	<b>Banco Intermedio</b>		<b>65,00</b>	<b>75,04</b>	<b>30,00</b>	
<b>Slanzi DVA 1550</b>	<b>Biella</b>	<b>( )</b>	<b>53,03</b>	<b>56,73</b>	<b>24,50</b>	
<b>Slanzi DVA 1550</b>	<b>Banco</b>	<b>( )</b>	<b>59,95</b>	<b>63,67</b>	<b>25,53</b>	
<b>Slanzi DVA 2200</b>	<b>Banco Posteriore</b>	<b>0</b>	<b>70,00</b>	<b>75,03</b>	<b>34,13</b>	

<b>Slanzi DVA 2200</b>	<b>Rasamento</b>	<b>( )</b>	<b>69,00</b>	<b>85,90</b>	<b>2,36</b>	
<b>Slanzi DVA 500</b>	<b>Biella</b>	<b>( )</b>	<b>55,35</b>	<b>59,09</b>	<b>25,00</b>	
<b>Slanzi DVA 520/920</b>	<b>Biella</b>	<b>( )</b>	<b>47,64</b>	<b>51,34</b>	<b>24,45</b>	
<b>Slanzi DVA 650/680</b>	<b>Biella</b>	<b>( )</b>	<b>57,12</b>	<b>60,84</b>	<b>27,00</b>	
<b>Slanzi DVA 680</b>	<b>Banco</b>	<b>0</b>	<b>58,00</b>	<b>63,04</b>	<b>30,25</b>	
<b>Slanzi DVA 800/1005</b>	<b>Banco Anteriore</b>		<b>55,00</b>	<b>70,00</b>	<b>30,10</b>	
<b>Slanzi DVA 800/1005</b>	<b>Banco Posteriore</b>		<b>55,00</b>	<b>70,00</b>	<b>35,10</b>	
<b>Slanzi S32 R40</b>	<b>Biella</b>		<b>40,00</b>	<b>50,00</b>	<b>53,00</b>	<b>45,00</b>
<b>Slanzi SA10/12</b>	<b>Biella</b>	<b>( )</b>	<b>25,00</b>	<b>31,00</b>	<b>25,50</b>	<b>20,00</b>
<b>Slanzi SA14</b>	<b>Biella</b>	<b>( )</b>	<b>30,00</b>	<b>36,00</b>	<b>30,00</b>	<b>24,00</b>
<b>Slanzi SA18</b>	<b>Biella</b>	<b>( )</b>	<b>40,00</b>	<b>48,00</b>	<b>40,00</b>	<b>32,00</b>
<b>Textile</b>	<b>Banco</b>		<b>45,00</b>	<b>55,04</b>	<b>38,00</b>	
<b>Vancini VM 15 DA</b>	<b>Banco Posteriore</b>	<b>0</b>	<b>66,04</b>	<b>76,02</b>	<b>55,00</b>	
<b>Vancini VM 20 DA</b>	<b>Banco Centrale</b>		<b>57,15</b>	<b>60,85</b>	<b>39,00</b>	
<b>Vancini VM 20 DA</b>	<b>Banco Posteriore</b>	<b>0</b>	<b>55,03</b>	<b>65,02</b>	<b>40,00</b>	<b>75,00</b>
<b>Vancini VM 20 DA</b>	<b>Banco Anteriore</b>		<b>55,03</b>	<b>65,02</b>	<b>25,00</b>	<b>75,00</b>
<b>Vancini VM 5 DA</b>	<b>Biella</b>	<b>( )</b>	<b>57,09</b>	<b>60,84</b>	<b>36,00</b>	
<b>Vancini VM 5 DA</b>	<b>Biella</b>	<b>( )</b>	<b>57,09</b>	<b>60,84</b>	<b>36,00</b>	
<b>Vancini VM HR192</b>	<b>Biella</b>	<b>( )</b>	<b>53,92</b>	<b>57,58</b>	<b>23,25</b>	